







	<p>A x1</p> <p>M4</p>	<p>B x12</p>	<p>C x12</p> <p>3.5x16</p>	<p>D x6</p> <p>20x20</p>	<p>E x4</p> <p>∅20</p>
--	-----------------------	--------------	----------------------------	--------------------------	------------------------



Температурный режим эксплуатации изделия  
допустимый диапазон +5С° до +40С°  
влажность от 30% до 60%



- (A) -1
- (B) -12



- (C) -12
- (D) -6
- (E) -4